Mint of the United States at Philadelphia, Pa.,

COINER'S OFFICE,

January 6th 1893.

Col O. B. Bosbyshell

Superintendent

Sir!

The Coining Press made by the Terracute Machine Co Bridgeport Ct. is not working satisfactory – the Coined Pieces are bruised on the edges (Cents) and all efforts on our part so far fail to remove the trouble. The System of feed attached to the Press requires alteration to suit the planchets.

I would respectfully suggest that the Manufacturers send some one here to look after this difficulty.

Very Respectfully

W. Deeds

Coiner

RG104 Entry-1 Box 179

NARA RG104, Entry 1, Box 179

Mint of the United States at Philadelphia, Pa.,
Coiner's Office,
January 6, 1893

Hon. O.C. Bosbyshell
Superintendent

Sir:

The coining press made by the Ferracute Machine Co. Bridgeport N.J. is not working satisfactory – the coined pieces are bruised on the edges (cents) and all efforts on our part so far fail to remove the trouble. The system of feed attached to the press requires alteration to suit the planchets.

I would respectfully suggest that the manufacturers send some one here to look after this difficulty.

Very Respectfully,
W.S. Steel
Coiner